

## Glossary

**R- Chart:** The R-Chart is used for control of process variability when the process dispersion is measured using ranges.

**S -Chart:** The S-Chart is used for control of process variability when the process dispersion is measured using standard deviations.

**CONTROL CHARTS FOR VARIABLES:** Measurements on any quality characteristic from a process working under a system of chance causes are expected to follow the Normal distribution

**Trial control limits and control limits:** The trial limits are control limits for analyzing the past data or at the initial stage of establishing control chart, calculated following the procedure explained.

**Attributes:** Characteristics that are measured as either "acceptable" or "not acceptable"; "conforms to specification" or "do not conform to specifications"; "go" or "no go" - thus have only discrete, binary, or integer values.

**Variables:** Characteristics those are measurable in numerical measurements on a continuous scale. e.g., Height, weight, diameter, kilogram, liter, temperature, volume...etc.